





Part Number	D119-796-011	Box Part Number	BX40	12 x 9 x 7
Description	Fwd Peg Step	Other Packaging	Uline S4488	
		Logo Decals		

## **Packaging Instructions and Decal Placement**

## D119-796-011

Place bubble wrap on bottom of box. Put in steps. Put hardware, clamp cushion and paperwork in same bag and place on top of steps in box. Put more bubble wrap to prevent movement. Apply label D2729-3 as per instructions in QSI 014.

D2729-4

N/A

D2729-3



Dart Aerospace Ltd. 1270 Aberdeen Street Hawkesbury, ON K6A 1K7 CANADA TEL.: 1 613 632-5200

**FWD PEG STEP** 

P/N: D119-796-011

**CHG002** 

**B/N: BXXXXXX** 

5,5/07/15

Revision: C

Date: 15.07.13